



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

SWA3-2

Job Sheet 182539



005302

Part No: SWA3-2

Job Qty: 1 ea

Part Name: Electric Swivel 3,000 lb Safe Work Load (1,360 Kg)



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 8/28/18

Job Tracking No:

Due Date: 10/22/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG SWA3 Rev 3

Ship Via:

5107709

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea		10/22/18	0.00	0.00	Start Up Small Fab-2		
110	Small Fab	1 pcs		10/22/18	0.00	2.00	Small Fab-6		AP
120	QC	1 pcs		10/22/18	0.00	0.00	QC5		SD
125	DC	1 pcs		10/22/18	0.00	0.00	DC		SD
130	Packaging	1 pcs		10/22/18	0.00	0.00	Packaging3		SD
140	QC21-FG	1 Ea		10/22/18	0.00	0.00	QC21		MD 18.09.07

Part Op 110 - -Assemble as per DWG. Sheet 1 ***All assembly to be done in accordance with SWA3 swivel manual*** Engrave Descriptions: T/N And / or S/N number as required Using Marktronic engraver as per DWG. Laser engrave dart logo as per DWG.

125 - Photocopy blue file OM & OOPM-SWA3A Rev3

130 - Bag and tag

GREASE NO. 7 AEROSHELL (M138724)

LOCTITE 242 (M138766)
SILICONE GE (M138942)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
188-FPSS-832-3/8	Set Screw	1 Ea (1 ea)	90-Start up Operation	5027242
92210A303	Flat Socket Cap Screw	4 pcs (4 ea)	110-Small Fab	5031243
EL-PLUG-F	3-Prong Female Spade Plug	1 Ea (1 ea)	110-Small Fab	5031223
EL-PLUG-M	3-Prong Male Spade Plug	1 Ea (1 ea)	110-Small Fab	5066781
EL314-SJTOW	Long Line Electrical Wire, 14/3 Gauge	6 ft (6 ea)	110-Small Fab	5047767
SWA3-100P	Upper End - Swa3 Swivel	1 Ea (1 ea)	110-Small Fab	5029397
SWA3-200	Lower End	1 Ea (1 ea)	110-Small Fab	5010109D
SWA3-300	Wire Clamp	2 Ea (2 ea)	110-Small Fab	5095875
SWA3-400	Button Head Screw	2 Ea (2 ea)	110-Small Fab	5098013
SWA3-500	Connector Bushing-230	1 Ea (1 ea)	110-Small Fab	5029401
SWA3-600	O-Ring	1 Ea (1 ea)	110-Small Fab	5097844
SWA3-700	9529K15 Bearing Balls - 1/4"	32 Ea (32 ea)	110-Small Fab	5093350
SWA6A-1900	1/4" Female Spade Connector	4 Ea (4 ea)	110-Small Fab	5073060
SWA6A-900A	Rotary Connector - 2 wire	1 pcs (1 ea)	110-Small Fab	5072695

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	188-FPSS-832-3/8	1	63	0
110-Small Fab	92210A303	4	112	0
	EL-PLUG-F	1	33	0

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

EL-PLUG-M	1	107	0
EL314-SJTOW	6	327	0
SWA3-100	1	0	0
SWA3-200	1	8	0
SWA3-300	2	33	0
SWA3-400	2	22	0
SWA3-500	1	0	0
SWA3-600	1	19	0
SWA3-700	32	1,024	0
SWA6A-1900	4	646	0
SWA6A-900A	1	8	0

Part Specifications

Specifications could not be found.

Plex 8/28/18 8:51 AM Dart.lajeunesse.marie

DART
AEROSPACE

1610 PONDICHIERRY ROAD
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S107709



Part: SWA3-2

Job No: 182539

Serial No/Batch: S107709

Revision: 3

Inspector:

Exp Date:

Instructions:

Date: 09/06/18

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	


Root Cause				FAULT CATEGORY			
Environment ☐	Design ☐	Doc/Data ☐	Equip/Tooling ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Handling/Pre ☐	Material ☐	Internal Transport ☐	Tribal Knowledge ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
LOA ☐	Substation ☐	Past Expiry Date ☐	Misidentified ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
				Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
				Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
				Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
				Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
				Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
				Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
				Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
				OTHER : ☐			

Work Order 182539

Customer _____

Number of Wires 2Date 2018/09/09Serial Number S107709

Number of Cycles	Load (Lbs.)	Action	Pass/Fail
1	3,000	Check for Conductivity against all wires.	- PASS
1	3,000	Check all wires for grounding against swivel body.	- PASS
1	1,500	Check for Conductivity against all wires.	- PASS
1	1,500	Check all wires for grounding against swivel body.	- PASS
1	750	Check for Conductivity against all wires.	- PASS
1	750	Check all wires for grounding against swivel body.	- PASS
1	0	Check for Conductivity against all wires.	- PASS
1	0	Check all wires for grounding against swivel body.	- PASS

Test Conducted By: ALAIN PATRY
TechnicianSignature: Sylvie Bouchard
QC/Small FAB / QASubmit